MARYLAND HISTORICAL TRUST DETERMINATION OF ELIGIBILITY FORM

NR Eligible: yes ____

Property Name: Morris Farm House	Inventory Number: CAR-255
Address: 13850 Cherry Lane	Historic district: yes X no
City: Ridgely Zip Code: 21657	County: Caroline
USGS Quadrangle(s): Ridgely	
Property Owner: State of Maryland's Department of Natural Resources	Tax Account ID Number: 010494
Tax Map Parcel Number(s): 23 Tax Map Number	er:13
Project: DNR Historic Documentation of Razings Agency	/: Maryland's Department of Natural Resources
Agency Prepared By: Historic Preservation Consultant	
Preparer's Name: Catherine Masek	Date Prepared: 1/26/2009
Documentation is presented in: MIHP form for Morris Farm House, CAR-255, b Farm House, CAR-255, by Catherine Adams Ma	
Preparer's Eligibility Recommendation: Eligibility recommended	X Eligibility not recommended
Criteria: A B C D Considerations: A B	BC _ D _ EF _ G
Complete if the property is a contributing or non-contributing resource	
Name of the District/Property:	
Inventory Number: Eligible: yes	s Listed: yes
Site visit by MHT Staff yes X no Name:	Date:
Description of Property and Justification: (Please attach map and photo)	
The Morris Farm House does not appear to meet the standards for eligibility for no Criterion A: No evidence has been uncovered that would indicate this site has significance becapattern of our history, as required of Criterion A. While the farm does have associpractices, the many historic structures of agricultural use that once existed on the plocal historical event, business or industry that the Starkey family were associated public recreation and the Tuckahoe State Park since 1974, and so an insufficient ar Furthermore, having been used as a rental property by the Department of Natural R for an educational or recreation-related purpose under State ownership.	ause it is associated with an event or broad ation with late 19th century agricultural property have been razed. There is no known with. The property has been associated with mount of time to have made any impact.
Criterion B: No person of significance is associated with the Morris Farm House. After comple owner 1848-1883, amassed a large contiguous tract of land of approximately 800 a impact or contributions at local or county level have been uncovered. Thomas St.	acres during his lifetime, but no significant
MARYLAND HISTORICAL TRUST REVIEW	
Eligibility recommended Eligibility not recommended >	190
	B _ C _ D _ E _ F _ G
MHT Comments:	*
Smathen Suga	2/12/09
Reviewer, Office of Preservation Services Reviewer, National Register Program	Date 2 12 0 Date

200900282

NR-ELIGIBILITY REVIEW FORM

CAR-255

Morris Farm House

Page 2

a farmer, but no other facts about his lfe are known at this time. Morris, owner 1942-1974, while a carpenter associated with Glenn L. Martin, Baltimore, is not known to have made significant contributions to either Baltimore or to the Ridgely area.

Criterion C:

This site contains a principal residence erected c. 1875-1925, in its original location and on original foundation. However, there have been architecturally unsympathetic changes to the house that have included: demolition and removal of gable end chimneys and interior mantels, interior overall insertion of artificial wall materials including Z-brick and wood veneer paneling, removal and replacement of all but three interior doors with plain hollow core doors, replacement of exterior doors, second floor plan changes, addition of vinyl windows, bathroom and kitchen renovations, exterior aluminum siding application and front porch replacement, well installation. The building is in fair condition, vacant since 2001, but deterioration is noted on the rear façade of the kitchen wing. Furthermore, the eight historic outbuildings that once lined the entry drive and were of agricultural usage no longer exist. These had included: granary, corncrib, tenant house, implement shed, privy, stable, smokehouse, cow barn. The three existing outbuildings date early- mid 20th century and are insignificant. They stand open and exposed to weathering, deteriorated and in a state of collapse.

In conclusion, there is insufficent evidence to consider the Morris Farm House property eligible for the National Register of Historic Places.

MARYLA	ND HISTO	DRICAL	TRUST	REVI	EW							
Eligibility recommended			Eligibility not recommended									
Criteria:	-	В	C	D	Considerations:	A	B	c	D _	E	F	G
	Review	er, Offic	e of Pres	servatio	on Services			Date			e s	
	Revie	wer, Nat	tional Re	egister l	Program	_		Date				

CAPSULE SUMMARY
Morris Farm House
MIHP #CAR-255
13850 Cherry Lane
Ridgely, Caroline County
c. 1875-1925
Public- within the Tuckahoe State Park

The Morris House property is located near the wooded marshlands of the Tuckahoe Creek, within the Tuckahoe State Park. Located in the northwestern quadrant of Caroline County, the park is linear in shape and follows the Tuckahoe Creek in a northsouth direction. The house is located on Cherry Lane, which is the eastern border of the park. A largely agricultural and rural area, the property is five miles northwest of the town of Ridgely. Approaching the park from Rte 304, Centreville- Ruthsburg Road, one turns south onto Rte 481, Ruthsburg Road, and enters the park on Crouse Mill Road. One crosses the Tuckahoe Creek, and marshlands, and turns north or left onto Cherry Lane. There are campgrounds and park lands located on the west side, while small farms line the east side of the flat, narrow, paved Cherry Lane. The white aluminum sided two storied L-shaped farmhouse built c. 1875-1925, is accessed via a narrow unimproved entry lane. A "street" of approximately nine outbuildings, historically of agricultural use, once lined this entry lane. Vacated by the State's last tenant in 2001, the house is in fair condition and the three standing outbuildings, which date to the earlymid 20th century, are deteriorated/ in a state of collapse. The approximately one hundred three acre lot was conveyed to the State's Department of Natural Resources in 1974.

The asphalt gable roofed, two story, frame house with brick foundation has a shed roofed, one story, frame addition of the mid 20th century located on the inside of the L. Simple in design, the house does display historic sash windows and decorative original fishscale shingles at attic level on all facades. During the mid twentieth century, electricity and indoor plumbing were added, interior alteration occurred. The following changes have occurred at the property which negatively affect the architectural integrity: demolition and removal of gable end chimneys and interior mantels, second floor plan changes, interior overall application of artificial wall materials including Z-brick and wood veneer paneling, removal and replacement of all but three interior doors, replacement of exterior doors, addition of vinyl windows, bathroom and kitchen renovations, exterior aluminum siding application, front porch replacement, well installation, and demolition of all historic agricultural structures.

Inventory No. CAR-255

Maryland Historical Trust Maryland Inventory of Historic Properties Form

historic	Starkey Farr	n House					
other	Morris Farm						
2. Location							
street and number	13850 Cherry	Lane				_ not for pu	ublication
city, town	Ridgely				_	vicinity	
county	Caroline						
3. Owner of	Property	(give names and	mailing address	es of all owne	ers)		
name	State of Maryla	and's Department of	Natural Reso	urces	166		
street and number	580 Taylor Av	enue, Tawes State	Office Bldg D-	3	telephone	410-260-8	932
city, town	Annapolis		state	MD	zip code	21401	
city, town	Denton	Caroline County Co tax ma		parcel 23			010494
5. Primary L	ocation o	f Additional	Data				
Contril Determ	outing Resource in nined Eligible for nined Ineligible fo	n National Register Di n Local Historic Distric the National Register/ r the National Registe	ct Maryland Regis			13	
Record	20	t or Research Report	at MHT				
Record	c Structure Repo		at MHT				

7. Description		Inventory No. CAR-255
Condition		
excellent good X_ fair	deteriorated ruins altered	

Summary:

The Morris Farm House is located on the northwest side of Cherry Lane, northwest of the town of Ridgely, Caroline County, within the Tuckahoe State Park. The farm is located approximately 500 feet south of Tuckahoe Creek on a parcel of land that includes both low marshlands and flat tilled fields. Historically part of the "Bradley or Branch farm", the Morris farm has a straight unimproved lane accessed via the narrow paved Cherry Lane. Along this entry lane there were eight structures in the 1920-30's, none of which currently exist other than the house. Three early-mid 20th century frame outbuildings do exist north and west of the house.

The three bay L-shaped cross gabled frame two story house with one story frame open porch is located north of the entry drive. Sheet metal simulating stone covers a brick foundation and horizontal aluminum siding covers horizontal wood siding on the exterior walls. Fishscale shingle exists only at the attic level, on all facades.

Comprehensive description:

The three bay two story frame house with asphalt shingle roof, metal gutters and downspouts, was built c. 1875-1925 with alterations through c. 1990, faces southeast towards Cherry Lane. Vinyl triple track storm windows cover double hung sash that is configured as two over one and three over one divided sash. A one story porch spanning the width of the front gable roofed portion was rebuilt in the late 20th century. The 1979 MIHP describes an porch that existed in this location as "screened porch with turned supports, brackets and pentels." An inaccessible basement/ crawl space is accessed via an exterior entry on the rear façade. There are no basement windows. A single flue exists on the rear kitchen wing, while chimneys existed at either end of the front gable roofed section in 1979. Exterior doors were replaced in the late 20th century except that door on the front façade. A shed roofed one story mid-late 20th century section is located ion the inside of the L.

On the front (east) façade, first floor, there are paired three/ one double hung sash on either side of a front door. Centered above each of these three bays is a single two/ one double hung sash on the second story. An unaltered two/ two double hung sash pointed window is located at attic level in the central bay. Wooden fishscale shingle surrounds this attic level window, recent metal gutters and downspouts hang from the steeply pitched gable roofline. A deep overhang is evident at attic level, while a shallower soffit / overhang is evident at second story roofline.

The side (south) façade, which is about 8 feet from the entry driveway, forms the outside wall of the L-shaped plan. The windows in the south gable end of the front section are off center, to allow for the chimney to be in the center of the wall. There is one 3/1 window on first floor and a 2/2 window on second floor. Fish scale shingle exists in the gable above that. The rear gable roofed kitchen wing is attached to the front section and is two storied, terminating in a brick chimney at its northernmost end. On the south façade of this kitchen wing are a three/ one double hung sash and a two/ two double hung sash windows at first floor level, while there is a two/ two double hung sash at second story level.

On the rear (west) façade is the gable end of the kitchen wing. A recently replaced door is located in the southernmost bay with a two over two double hung sash window above it. The basement/ crawl space is accessed via an exterior opening north of the door.

On the north façade is access into the house via the one story shed roofed bathroom wing. A recently replaced door enters the wing at grade and a 1/1 window is located in the bathroom to the west of the door. On the second story of this façade in the kitchen wing is a two/ two double hung sash window. Also in the center of the L-shaped house are two windows, located north of the first floor exterior side entry. A 3/1 double hung sash window is on the first floor and a 2/2 hung sash is at second story level. There are two windows in the north façade, which mirror those in the south façade of the front gable end section of the house. While those windows in the south façade are west of the chimney location, the windows in the north façade are located east of the chimney location. Fish scale shingles exist in the attic level, north gable end, mirroring those on the south gable end.

Inventory No. CAR-255

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Name Continuation Sheet

Number 7 Page 1

One enters the house via the main entry in the center bay on the front (east) façade. The doorway features a wooden door with single clear glass pane in the upper half and three horizontal panels in the lower half. Inside, one is standing in the original parlor. There is a straight run wooden staircase with simply turned newel post and balusters located on the west wall. Below the staircase/ carriage, the triangularly shaped woodwork panel is covered with painted thin wood paneling. Immediately east of the staircase and free standing in the room are two columns and a beam running north to south, seemingly inserted for structural stability. "Z"- brick, a thin veneer brick, covers the north fireplace wall, including the original mantel location.

A simply decorated wall, pierced by three openings, separates the parlor from the dining room. The wall features a center doorway with flanking half walls. On the south wall is a thin veneer like paneling flanking a brick flue, where originally a mantel and fireplace had been located. A door in the west wall of the dining room leads to the kitchen, which was completely renovated in 1996. A flue in the west wall of the kitchen is enclosed on the interior. The exterior rear door in the kitchen's west wall was replaced in 1996. Three original interior wood 4 panel doors exist inside the house- one is located in the dining room at a closet and another is between the kitchen and the bathroom. The bathroom, located north of the kitchen in the shed roofed addition, is a 1996 replacement, including piping and plumbing. A new exterior well was added at the same time. A utility or mud room, with washer /dryer stands east of the bathroom in the shed roofed addition. An original exterior window in the kitchen is evident in this mud room. The sash has been infilled, but frame remains.

On the second floor, there is Z-brick, a thin veneer brick, covering the north and south fireplace walls and thin wood veneer paneling covering all other interior walls. Modern walls covered with thin wood veneer paneling have been inserted on the second floor to create a small hall at the top of the stairs. Modern closets with sliding hollow wood doors exist in the north bedroom and in the master bedroom over the kitchen. One historic door exists on the second floor and it is located between the front south bedroom and the rear master bedroom. The west chimney flue rises in the closet of the master bedroom. All of the walls in the master bed room and its closet are covered in thin wood veneer paneling. No attic access was apparent.

The current vertically sided frame outbuildings consist of a one bay frame garage, an animal shed and a storage building. The garage, which is completely covered in vegetation, is located southwest of the house. In the gable roofed entry facade there is no door. Roofing on the south side has collapsed to the interior. This early-mid 20th century structure has a small window on the west façade. The early- mid 20th century vertically sided wood animal shed is located west of the garage and the house. Its roof consists solely of rafters, and the remainder has collapsed to the interior. There is an open doorway located in the west gable wall. Window openings are located in the north and south walls. No door or window sashes exist. Inside, there is a concrete foundation evident beneath all walls and a concrete trough located on the north wall. Wall and roofing materials are collapsing into the interior. A vertically sided wooden storage shed with doorway on its east gable end is located immediately west of the house. This mid-late 20th century storage structure, lacking door, has a raised floor and its condition is better than other outbuildings. The four foot tall grasses growing on all sides of the house and around existing outbuildings limit the ability to seek foundations or remnants of earlier structures. Historic structures of agricultural use did exist. The following outbuildings had been located along the entry lane of the Morris farm, but no longer exist: Immediately opposite/ south of the house was a 40' x 30' two story cow barn with loft. There was a stable/ wagon shed west of this cow barn. On the north side of the entry drive, going west from the house was located a privy, smokehouse, and water trough. West of these structures was an implement shed. West of the implement shed was a 20 x 20' two story granary, a corncrib and a tenant house. The tenant house has been descried as two stories; three bays with center door in south façade, clapboard covered exterior walls and with cream colored exterior paint. (Bill Cooper, longtime neighbor, 12/08 telephone interview) See historical site plan attached herein.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No. CAR-255

Name Continuation Sheet

Number 7 Page 2

The condition of the house was recorded as "good" when visited in 1979; however, its condition is currently "fair." The rear kitchen wing is in the poorest condition, where vegetation and water has begun to infiltrate the west wall. Outbuildings, especially the animal shed and garage are in a state of collapse, and stand open to the weather.

8. Signific	cance			Inventory No. CAR-255
Period1600-16991700-1799 X1800-1899 X1900-19992000-	Areas of Significance agriculture archeology architecture art commerce communications community planning conservation	Check and j	ustify below health/medicine industry invention landscape architecture law literature maritime history military	performing arts philosophy politics/government e religion science social history transportation other:
Specific dates			Architect/Builder	
Construction d	lates c. 1875-1925			
Evaluation for:				
11	_National Register	N	laryland Register	not evaluated

Summary:

The Morris House, while altered through the late 20th century, stands as a simple L-shaped late 19th century farmhouse in its original location, but without its historic surrounding agricultural structures intact. Historically, the house probably dates to c. 1885, when the 126 acre parcel was conveyed to Thomas B. Starkey, as the result of the division of lands of his father, John E. Starkey. Utilized as a working farm by both the Starkey and Morris families, the property was used as a rental for the last 25 years by the State of Maryland. Indoor plumbing and electricity was added by the Morris family. Some changes/alterations probably occurred to interior woodwork and outbuildings. Other changes to the property occurred after it was conveyed to the State of Maryland. Significant alterations have included: removal of front chimneys and mantels, interior door and room plan changes, interior wall surface changes, bathroom and kitchen renovations, exterior aluminum siding application, front porch replacement, exterior door replacements and vinyl window additions, demolition of agricultural structures.

Narrative:

The late 19th century Morris House may have been constructed as early as 1875, in accordance with the State of Maryland's Department of Assessments and Taxation form, but most likely would have dated to c.1885, when Thomas B. Starkey acquired the property. (Caroline County Commission Book 1, Liber JHF No. E, Folio 298-317)

John E. Starkey, father of Thomas, became heir to seven parcels of land in 1856 from John Bradley, via Abraham Jump. Totaling about 960 acres, these lands appears to have been located in that geographic area between Bradleysburg /Hillsboro area and Bridgetown and between Tuckahoe Creek (in both Caroline and Queen Annes Counties) and Purnells See attached photocopy of 1873 map of Caroline, Queen Anne and Talbot Counties. The parcels have been described as follows: "a parcel of land on the main road leading from Jumptown to Turner's Mill, called the Bradley Farm, composed of parts of "Colne Rectified" on Piney Branch, containing 100 a.- also "New Buckby," 100 a.- also part of "Godfrey's Folly containing 33 ac.- also part of "New Nottingham Rectified," 17 a.- also part of "Cow Range" on the south side of an old millpond called Wooters' 16 a.- also part of "New Nottingham Rectified," adjoining David Kennedy's part and part formerly belonging to John Bradley, Sr., containing 27 3/4 a.- also part of "Godfrey's Folly" on the east side of Tuckahoe Creek and adjoining the mill seat commonly known as Rickett's Mill and also near an old mill called Wooters' Mill- adjoining "New Buckby" on the south side of a branch of Wooters' Millpond, purchase by John Bradley, deceased, of John Due; Samuel Pritchett and Serena A. Pritchett, heirs of James Due, deceased, containing 10 acres- which all constitute the Bradley farm, conveyed to Abraham Jump, deceased, by Zabadial Potter, Trustee for the sale of the real estate of John Bradley, deceased, 11 May 1844..." (Caroline County Land Record Book 24, Vol. CC, 1855-1858, p. 40, compiled by Bernice Leonard) Starkey added to these parcels, his acquisitions, recorded in the Land Records of Caroline County, date primarily from the 1840-1850's. (Deed, Liber JHT, X, Folio 226, 1848)

John Starkey had two wives and eight children. His first wife, Cathalinda (also spelled "Ethelinda") Barcus, who he married in 1838 in Queen Anne's County, was the daughter of a successful miller associated with the Crouse's Mill. (Chesapeake Cousins, Vol. 17, No. 1, p. 36- Ancestor chart) Her mother, member of the Turner family who owned the

Inventory No. CAR-255

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Name Continuation Sheet

Number 8 Page 1

Turner's Mill mentioned above, also was a miller. Ethelinda died in 1868. (Caroline County Marriage/Death/Birth Records, 1850-1880, by Edward Wright, p. 10, Newspaper abstracts) He married a second time at age 46, six months after Ethelinda's death, in 1869, to the widow, Mary E. Mullikin, age 40. At that time, he was described as a "farmer" and Mary was described as a "housekeeper." (Caroline County Marriage Licenses 1865-1886), compiled by Dorothy H. Baird and Louise A. Scott, p. 100) Starkey continued to be listed as a farmer in 1878, when a list of merchants and farmers was compiled. (Chesapeake Cousins, Vo. 18, No. 2, Caroline County Merchants and Farmers, 1878, p. 31 & 34) Suffering marriage difficulties, there is recorded a document describing alimony and a land conveyance to Mary E. Starkey dated 1876. (Cont., Liber JWT 37, Folio 385)

Starkey was also a slaveholder. In 1855, "a Negro woman Amanda" was conveyed for \$150.00 to John Sangstron for a period of 7 years. "Her issue to be slaves for life." (Caroline County Record Book 24, Vol. CC 1855-1858 compiled by R. Bernice Leonard, p. 40) There is also a recorded "Bill of Sale" for a "Negro boy" costing \$200.00 in 1859. (B of S, Liber RJ 29, Folio 155)

At the death of John Starkey in 1883, his lands were called the "Bradley Farm" and these were divided among his eight heirs. After the completion of a survey in 1884, which survey is included in the above referenced Commission Book #1, John Starkey's lands were divided and the 126 acre Morris House property was conveyed to John's youngest (20 yr old) child, Thomas B. Starkey in 1885. See photocopies of 1884 survey related to Thomas B. Starkey.

At this time, Caroline County's economy was largely agricultural and rural in nature and the Ridgely area was especially well known for its fields of excellent quality strawberries. With the development of the town of Ridgely, for which a survey is dated 1867, the area began to grow in population. (JOK Walsh, meeting- 10/08) A Maryland Agricultural College, basket factory, several canning factories, and the Armour strawberry plant and poultry farms existed in the Ridgely area by 1920. (Emory Dobson, A History of Caroline County, 1920, p.300-306)

Thomas B. Starkey and his wife, Ida, would have built the L-shaped house and most of the outbuildings/ agricultural structures in the late 19^{th-}-early 20th century. Thomas (1871-1944) and Ida (1868-1962) are both buried at Greenmount Cemetery, Hillsboro, MD (Beneath These Stones, Cemeteries of Caroline Co., Vol. 11, p. 133) They had one child, John, who died approximately 2007 at age 100. (Cooper, telephone interview, 1-09) So, it would seem likely that Thomas married and had the house principally constructed by c. 1897. No photographs of the outbuildings are known to exist, but would have been constructed under his ownership as well. (See site map showing approximate locations of historic outbuildings based upon verbal descriptions by B. Cooper, 12/08.)

George Morris and his wife, Mary, acquired the 126 acre property in 1942, by which time the house and its agricultural structures would have been completed. (Deed, Liber WAC & DRH 102, Folio 243) Morris was known to have been a carpenter who worked for Glenn L. Martin, Baltimore, and relocated to Caroline County in 1943. He is known to have added the one story shed roofed addition in the center of the L shaped house, in order to house a bathroom. Electricity poles and lines reached Cherry Lane farms in 1946, and this would have been during Morris' ownership as well. (Cooper, 1/09 telephone communication) He also probably replaced the front door at the main entry, made some woodwork changes/ artificial wall applications, added the one car garage, and may have razed some of the agricultural structures.

The property, reduced to approximately 103 acres, was conveyed in 1974 to the State of Maryland. (Deed, Liber 187, Folio 38). It was used as a rental property from approximately 1977 to 2001. There have been architecturally unsympathetic changes to the property that included: demolition and removal of gable end chimneys and interior mantels, interior overall insertion of artificial wall materials including Z-brick and wood veneer paneling, removal and replacement of

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No. CAR-255

Name Continuation Sheet

Number 8 Page 2

all but three interior doors with plain hollow core doors, second floor plan changes, replacement of exterior doors, addition of vinyl windows, bathroom and kitchen renovations, exterior aluminum siding application and front porch replacement, well installation, demolition of outbuildings. Some of this activity occurred in the 1990's, documented in DNR Annual Lease Inspection sheets. The property, vacant since 2001, has suffered limited vandalism and damage. Windows and the front door have been covered for protection. While the house is, generally, in fair condition, the rear kitchen wing is deteriorating. The outbuildings- particularly, the garage and animal shed, are in a state of collapse. All three standing outbuildings are open and exposed to weathering. The grounds are deteriorated and unkempt.

9. Major Bibliographical References

Inventory No. CAR-255

Primary Sources include:

Cooper, Bill, longtime resident of Cherry Lane, telephone communications 12/08- 1/09.

Dietrich, Paul, Tuckahoe State Park employee, site visit meeting, 9/08.

Ohler, John, Manager, Tuckahoe State Park, email correspondence 9/08-12/08.

Terebey, Jane. Library Associate, Caroline Co. Public Library, Denton, MD, email & telephone correspondence 1-09.

Walsh, J.O.K., Caroline Co. Historical Society, meeting -10/08, email correspondence- 11-12/08.

10. Geographical Data

Acreage of surveyed property .5 ac Acreage of historical setting .5 ac. Quadrangle name RidgelyMD Quad

Quadrangle scale: 1:24000

Verbal boundary description and justification

Cherry Lane is the east boundary line, the treeline south of the garage is the south boundary line, the treeline west of the animal shed is the west boundary line and the landscaped boundry line north of the house is the north boundary line.

11. Form Prepared by

name/title	Catherine Adams Masek		
organization	Historic Preservation Consultant	date	1/24/09
street & number	124 St. Andrews Road	telephone	410-987-8519
city or town	Severna Park	state	MD

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust Maryland Department of Planning 100 Community Place Crownsville, MD 21032-2023 410-514-7600

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No. CAR-255

Name Continuation Sheet

Number 9 Page 1

Anne Arundel County Public Libraries:

Dobson, Emory. History of Caroline County, Denton: Regional Publishing Co, 1920, republished 1971.

Website: <MdLandRec.Net>

"Deed," between George W. Morris & Mary A., his wife, and the State of Maryland for the Department of Natural Resources, Liber 187, Folio 38, 1974, 103.137 acres.

"Deed" between Thomas B. Starkey & Ida, his wife, and George W. Morris & Mary, his wife, Liber WAC & DRH 102, Folio 243, 1942, 126 acres.

Caroline County Commission Book 1, Division of the "Bradley farm" (800 acres), lands of John E. Starkey, deceased, 1883, among his 8 heirs. Liber JHF No. E, Folio 298-317, microfilm. Survey dated 12/1884, commission proceedings dated 1885. The Tract #1, 126 acres, included the Morris House property, and was conveyed to youngest (20 yrs old) son, Thomas B. Starkey.

Estate settlement for Abraham Jump, dec'd 1844, Caroline Co. Land Records Books, book 24, Vol. CC, 1855-1858, p. 40.

Maryland State Archives:

Martenet, Walling & Gray. Maps of Caroline, Queen Anne and Talbot Counties, 1873.

Microfilm collection- Caroline County Commission Book 1, 1885 Division of Lands of the deceased John E. Starkey.

Wheeler Goodman Masek One Annapolis Street #100 **Annapolis Maryland 21401**

Project MORRIS HOUSE, TUCK AHOE S.P.

CARProject # 255 Date 12/08 Page

CHERRY LANE RIDGELY VIC.

CAROLINE CO.
HISTORICAL SITE PLAN

CBASED ON, DESCRIPTION)

V. 410.841.6787 F. 410.841.5523 www.wgm-arch.com NO SCALE 500't TO SWAMPLAND AROUND TUCKAHOE CASEK TENANT HOUSE LORNURIB LATER GRANARY ANIMAL SHED IMPLEMENT SHED LAVER 1 STABLE GARAGE, SMOKEHOUSE 1 PRIVY LAJER-STORAGE SHED XNIMAL COW BARN TROUGH STRY MAIN HOUSE CHERRY LANE

Proje Proje	ct ct#	MOR 255 HER AROL	PY INE	HOUS 12/0 LANE CO.	E, TU 8 PLA	Page DOELY TON)	HOES,	P	\	NC	ARCHITECT + INTERIO	Wheeler Goo One Annapoli Annapolis Ma V. 410.841.6787 F. 410.841.5523 www.wgm-arch	is Street #100 Iryland 21401
	CE	BAS	ED 0	N, DE	SCRIP	770N)							
	N	0 5	CAL	F					1				
									/				
								++t	500	1+ 1	S C	PI ALID	
									AROU	ND TE	O SWAM	CREEK	
	-								7				
										TENA		1-1-1-	
										House			
									-				
									110	LORNE	RIB		
	9					LATE	PL SHED			7	ANARY		
						BAIN	1C SHED			100	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
			+			1 1 5	2)		Ц—	-			
D-			-					1.1	-				
								$\perp \perp \downarrow \downarrow$	12				
								4 1 1		IMPLE	MENT		
					17					SHED			
				LAVER	1	[STABLE						
				GARAS	6,	1 1							
							ami	KEHOUS	4		100		
								T 003	H		1 PRIVY		
								+ + +	Ħ		LATER STORAGE		
			-				Cow,	1-1-1	X	Ulmar!	SHED		
							BARN		YX	OUGH			
											•		
								100	1				
								Z Z	4	7			
								MRY		MAIN	HOUSE		
								SAM					
								শ্					
					CHE	RRY	LAN						
- 2		<			000	/	Chio				→ ·		
					1	1-1-1		+				+	

Wheeler Goodman Masek Project MORRIS HOUSE, TUCKAHOE S.P. One Annapolis Street #100 CAR-Project # 255 Date 10/08 Page **Annapolis Maryland 21401** CHERRY LA. RIGGELY VIC. CARDLINE CO. V. 410.841.6787 F. 410.841.5523 FIRST FLOOR PLAN + INTERIORS www.wgm-arch.com SCALE: 1 = 1 RESOURCE MAPISITE PLAN-NO SCALE WOOD PORCH T+G CEILING MAIN ENTRY SIMULATED BRICK HINT WALL PANELING FLUE DINING RM PARLOR 1/2 WALL PAINTED WOOD PANELING I CL UTILITY I COVERED WINDOW KITCHEN BATH BASEMENT ENTRY -COLLAPSED-RESOURCE MAP/SITE PLANS STORAGE SHED MIGHATE ZOTHC. MAIN ANIMAL (PIG)? 2-LANE ENTRY HOUSE CHERRY LANE 20th GRAVELY DIRT DRINEWAY ONE CAR GARAGE 20thc, RIDGELY


Wheeler Goodman Masek One Annapolis Street #100 Annapolis Maryland 21401

V. 410.841.6787 F. 410.841.5523

Project MORRIS HOUSE, TUCKAHOE S.P.


CARS

Project # 255 Date 10 08 Page CHERRY LA, RIDGELY UK, CAROLINE CO. SECONDFL. PLAN




MAP OF TUCKAHOE STATE PARK- COURTESY OF MARYLAND'S DEPARTMENT OF NATURAL RESOURCES WEBSITE

Map 2 of Tuckahoe State Park




PHOTOCOPY OF 1873 MAP OF CAROLINE, QUEEN ANNES AND TALBOT COUNTIES BY MARTENET, WALLING & GRAY.


APPROXIMATE LOCATION OF JOHN E. STARKEY PROPERTY IDENTIFIED. COURTESY OF THE MARYLAND STATE ARCHIVES.



LOT #1- CONVEYED TO THOMAS B. STARKEY, MINOR.
HAND DRAWN SURVEY OF THE LANDS OF JOHN E. STARKEY,
DECEASED 1883. BY JOHN WHITAKER, SURVEYOR, DECEMBER 3, 1884.
COURTESY OF CAROLINE COUNTY COMMISSION BOOK 1,
MARYLAND STATE ARCHIVES



LOT #1 ½ -LOCATED ON MD RTE 287/313, NOT MORRIS HOUSE PROPERTY-CONVEYED TO THOMAS B. STARKEY, MINOR. HAND DRAWN SURVEY OF LANDS OF JOHN E. STARKEY, DECEASED 1883. BY JOHN WHITAKER SURVEYOR, DECEMBER 3, 1884. COURTESY OF CAROLINE COUNTY COMMISSION BOOK 1, MARYLAND STATE ARCHIVES.






CAR-255 MORRIS HOUSE RIDGELY VIC, CAROLINE CO. CHERRY LANE TUCKAHOE S.P. C. A. MASEK FRONT (EAST) FACADE, SITE LOFL



CAR-255 MORRIS HOUSE RIDGELY VIC. CAROLINE CO. CHERRY LANE TUCKAHOE S.P. C.A. MASEK 9/08 MD SHPO FRONT (EAST) FACADE-HOUSE 2 OF 6




CAR-255 MORRIS HOUSE RIDGELY VIE. CAROLINE CO. CHERRY LANE TUCKAHOE S.P. C. A. MASEK 9/08 MD SHPO REAR (WEST) FACADE 30F6



CAR-255 MORRIS HOUSE RIDGELY VIC., CAROLINE CO. CHERRY LANE TUCKAHOE S.P. C. A. MASEK 9/08 MD SHPO DETAIL- EAST FACADE WINDOW 4 OF 6



CAR-255 MORRIS HOUSE RIDGELY VIC., CAROLINE CO. CHERRY LANE TUCKAHOE S.P. C, A, MASEK 9/08 MD SHPO INTERIOR-PARLIR - WEST WALL 50F6



CAR-255 MORRIS HOUSE RIDGELY VIC, CAROLINE CO. CHERRY LANE TUCKAHOE S.P. C. A. MASEK 9/08 MD SHPO SHED WEST OF HOUSE - ZOTH C. 6 OF 6

MARYLAND HISTORICAL TRUST

DNR 81-85

MAGI # 0602553604

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

	NAME					
	HISTORIC					
	AND/OR COMMON	Morris Farm House				
2	LOCATION	N				
	STREET & NUMBER	West side of Che	erry Lane			
	CITY, TOWN			CONGRESSIONAL DISTR	ICT	
	Tuck	kahoe State Park _	VICINITY OF	First		
-		dgely , Md		Caroline		
3	CLASSIFIC	CATION				
	CATEGORY	OWNERSHIP	STATUS	PRES	ENTUSE	
	DISTRICT X_BUILDING(S)STRUCTURESITE	X_PUBLICPRIVATEBOTH PUBLIC ACQUISITION	XOCCUPIED UNOCCUPIED WORK IN PROGRESS ACCESSIBLE	AGRICULTURECOMMERCIALEDUCATIONALENTERTAINMENT	MUSEUM X_PARK X_PRIVATE RESIDENCERELIGIOUS	
and the last	OBJECT	_IN PROCESS	YES: RESTRICTED	GOVERNMENT INDUSTRIAL	_SCIENTIFIC _TRANSPORTATION	
_		BEING CONSIDERED	YES: UNRESTRICTED	MILITARY	_OTHER:	
4	NAME Maryland St	F PROPERTY tate Dept. of Natur	X NO			
4	NAME Maryland St STREET & NUMBER	F PROPERTY	X NO	MILITARY		
4	NAME Maryland St STREET & NUMBER	F PROPERTY	X NO	_MILITARY elephone #:		
4	NAME Maryland St STREET & NUMBER Tawes State CITY. TOWN Annapolis	F PROPERTY	XNO ral Resources To	_MILITARY elephone #: state, z	_OTHER:	
4	NAME Maryland St STREET & NUMBER Tawes State CITY. TOWN Annapolis LOCATION COURTHOUSE.	F PROPERTY Late Dept. of Nature Office Building NOF LEGAL DESCR	XNO ral Resources To vicinity of RIPTION L	_MILITARY elephone #:	_OTHER:	
4	NAME Maryland St STREET & NUMBER Tawes State CITY. TOWN Annapolis LOCATION COURTHOUSE.	F PROPERTY Late Dept. of Nature Office Building	XNO ral Resources To vicinity of RIPTION L	_MILITARY elephone #: state, z Md. diber #:	_OTHER:	
4	NAME Maryland St STREET & NUMBER Tawes State CITY. TOWN Annapolis LOCATION COURTHOUSE. REGISTRY OF DEEDS, STREET & NUMBER CITY. TOWN	F PROPERTY Late Dept. of Nature Office Building NOF LEGAL DESCR	XNO ral Resources To vicinity of RIPTION L	_MILITARY elephone #: state, z Md. diber #:	_OTHER:	
	NAME Maryland St STREET & NUMBER Tawes State CITY, TOWN Annapolis LOCATION COURTHOUSE. REGISTRY OF DEEDS, STREET & NUMBER CITY, TOWN Den	F PROPERTY Late Dept. of Nature Office Building N OF LEGAL DESCR	Tal Resources To VICINITY OF RIPTION L. F. Courthouse	MILITARY elephone #: STATE, Z Md. diber #: colio #:	_OTHER:	
	NAME Maryland St STREET & NUMBER Tawes State CITY, TOWN Annapolis LOCATION COURTHOUSE. REGISTRY OF DEEDS, STREET & NUMBER CITY, TOWN Den	F PROPERTY Late Dept. of Nature Office Building N OF LEGAL DESCR	Tal Resources To VICINITY OF RIPTION L. F. Courthouse	MILITARY elephone #: STATE, Z Md. diber #: colio #:	_OTHER:	
	NAME Maryland St STREET & NUMBER Tawes State CITY, TOWN Annapolis LOCATION COURTHOUSE. REGISTRY OF DEEDS, STREET & NUMBER CITY, TOWN Den	F PROPERTY Late Dept. of Nature Office Building N OF LEGAL DESCR	Tal Resources To VICINITY OF RIPTION L. F. VICINITY OF SURVEYS	MILITARY elephone #: STATE, Z Md. diber #: colio #: STATE Md.	_OTHER:	
	NAME Maryland St STREET & NUMBER Tawes State CITY. TOWN Annapolis LOCATION COURTHOUSE. REGISTRY OF DEEDS, STREET & NUMBER CITY. TOWN Den REPRESEN TITLE	F PROPERTY Late Dept. of Nature Office Building N OF LEGAL DESCR	Tal Resources To VICINITY OF RIPTION L. F. VICINITY OF SURVEYS	MILITARY elephone #: STATE, Z Md. diber #: colio #:	_OTHER:	

CONDITION

CHECK ONE

CHECK ONE

EXCELLENT

__DETERIORATED

_UNEXPOSED

_UNALTERED

XORIGINAL SITE

X_GOOD _FAIR

RUINS

XALTERED

__MOVED

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Morris Farmhouse, located on the west side of Cherry Lane within Tuckahoe State Park is a two storey, three bay structure with a lower two storey rear addition. The entire house has been aluminum-sided thus obscuring window and doorway surrounds and clapboard type. Both sections mest on brick foundations.

The east facade of the main block is distinguished by a one storey screened porch with turned supports, brackets and pentels. A central doorway is flanked by double windows. 3/1 sash windows with 2/2 sash mark the three corresponding openings on the second storey. A lancet 2/2 sashed window surrounded by fishscale shingles punctuates the centrally pitched gable. The asbestos shingled roof is further defined by corbel capped brick interior chimneys at both gable ends.

The north and south facades carry identical fenestration: an assymetrically placed 3/1 window surmounted by a 2/1 sashed window. The fishscale shingles are repeated in the pediment area of the gables.

The two storey, two bay el projects from the two southernmost bays. The south facade is defined by two 2/1 sashed windows on the first storey and a centrally located 2/1 sashed window on the second storey. A shed roofed addition extends across the first storey of the north facade. A doorway in the east bay and a 2/1 sashed window in the west bay characterize this addition. A 2/1 sashed window is centrally located on the second storey of the north facade. Another entrance is found on the west facade. Above it is a 2/1 sashed window. An interior brick chimney rises from this gable end.

Various outbuildings are located to the west of the farmhouse.

8 SIGNIFICANCE

SPECIFIC DAT	EC	BUILDER/ARCH	HITECT	
		INVENTION		
_№ 900-	COMMUNICATIONS	INDUSTRY	POLITICS/GOVERNMENT	_OTHER (SPECIFY)
_1800-1899	COMMERCE	_EXPLORATION/SETTLEMENT	PHILOSOPHY	_TRANSPORTATION
_1700-1799	ART	ENGINEERING	MUSIC	THEATER
1600-1699	ARCHITECTURE	EDUCATION	MILITARY	_SOCIAL/HUMANITARIA
1500-1599	X.AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE
_1400-1499	ARCHEOLOGY-HISTORIC	CONSERVATION	_LAW	SCIENCE
PREHISTORIC	_ARCHEOLOGY-PREHISTORIC	COMMUNITY PLANNING	_LANDSCAPE ARCHITECTURE	RELIGION
FRIOD	AF	REAS OF SIGNIFICANCE CH	ECK AND JUSTIFY BELOW	

STATEMENT OF SIGNIFICANCE

The Morris dwelling is a typical late nineteenth/early twentieth century farm of the Eastern Shore. Despite the remodeled interior and the aluminum-sided exterior, the main house with its attendant outbuildings contributes to the rural character of the area.



The Morris Farm should continue as an income producing rental property of the Department of Natural Resources. The main house and the majority of the nearby outbuildings appear to be in good condition.

A great number of similar farms along Cherry Lane and Eveland Road have disappeared. The Morris complex should not become another casualty.

Maryland

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF	NECESSARY
OGEOGRAPHICAL DATA ACREAGE OF NOMINATED PROPERTY	A PERSON OF THE SAME AND A SAME A
	are the search same search of the contraction of
VERBAL BOUNDARY DESCRIPTION	ANGEL ME OF THE PARTY OF THE PA
26 6 8 8	Date of the second of the
LIST ALL STATES AND COUNTIES FOR PRO	PERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES
STATE	COUNTY
STATE	COUNTY
11 FORM PREPARED BY	
NAME / TITLE	
Bridget M. Deale, Historic S	Sites Surveyor
ORGANIZATION	DATE
Maryland Historical Trust	August, 1979
STREET & NUMBER	TELEPHONE
21 State Circle	269-2438
CITY OR TOWN	STATE

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.


RETURN TO: Maryland Historical Trust

Annapolis

The Shaw House, 21 State Circle

Annapolis, Maryland 21401

(301) 267-1438





CAR-255-DNR BI-85

MORRIS FARMHOUSE WEST SIDE OF CHERRY LANE RIDGELY, MARY LAND

TUCKAHOE STATE PARK 5/79; BMD



DNR 81-85
MORRIS FARMHOUSE
WEST SIDE OF CHERRY LANE
RIDGELY, MARY LAND
COT. 255
TICKAHOE STATE PARK
S.E. ELEVATION
5/79; BMD

C-11 250